

Tower ASR-1004723 - Sector B

Data Capture & Analysis Report

DW-RPT-TEL-2026-0014

Revision 1 / Illustrative

Finding DW-FND-ASR1004723-001

PRIMARY INSPECTION FINDING

Mount cracking and corrosion at upper fastener

Surface cracking and corrosion were identified around the upper Sector B antenna-mount fastener.

FINDING ID


DW-FND-ASR1004723-001

ASSET CONTEXT

ASR-1004723 / Sector B / Upper mount

SOURCE RECORDS

RGB-ASR1004723-021



Status

Open

Disposition

Engineering Review Required

Priority

P1 - High

Confidence

Moderate

1 / Observed

Registered source capture

RGB-ASR1004723-021

2 / Correlated

Asset and historical context

ASR-1004723 / Sector B / Upper mount

3 / Determined

Human-reviewed finding

DW-FND-ASR1004723-001

4 / Action

Targeted investigation

Qualified review follows

Recommended further investigation

Complete a qualified tower inspection, verify fastener torque, and obtain mount structural review.

Illustrative mock-up only. Measurements, findings, and dispositions require validation before issuance.