

Structure TX-884 - Phase B

Data Capture & Analysis Report

DW-RPT-ETR-2026-0031

Revision 1 / Illustrative

Finding DW-FND-TX884-001

PRIMARY INSPECTION FINDING

Elevated connection temperature with visible corrosion

A localized thermal rise and corrosion were identified at the Phase B conductor-clamp connection.

FINDING ID


DW-FND-TX884-001

ASSET CONTEXT

North Valley Circuit / TX-884 / Phase B clamp

SOURCE RECORDS

IR-TX884-031 / RGB-TX884-017



Status Analyzing	Disposition Further Investigation Required	Priority P0 - Critical	Confidence High
1 / Observed Registered source capture IR-TX884-031 / RGB-TX884-017	2 / Correlated Asset and historical context North Valley Circuit / TX-884 / Phase B clamp	3 / Determined Human-reviewed finding DW-FND-TX884-001	4 / Action Targeted investigation Qualified review follows

Recommended further investigation

Initiate utility review, confirm under representative load, and perform a qualified de-energized connection inspection.

Illustrative mock-up only. Measurements, findings, and dispositions require validation before issuance.