

North Municipal Tank - Seam V-08

Data Capture & Analysis Report

DW-RPT-WTR-2026-0009

Revision 1 / Illustrative

Finding DW-FND-NWT-001

PRIMARY INSPECTION FINDING

Coating failure with active corrosion at shell seam

Coating delamination and corrosion were identified along vertical shell seam V-08 and an adjacent support connection.

FINDING ID


DW-FND-NWT-001

ASSET CONTEXT

North Municipal Tank / Upper shell / Seam V-08

SOURCE RECORDS

RGB-NWT-008 / GEO-NWT-003



Status	Disposition	Priority	Confidence
Open	Corrective Action Required	P1 - High	High
1 / Observed	2 / Correlated	3 / Determined	4 / Action
Registered source capture RGB-NWT-008 / GEO-NWT-003	Asset and historical context North Municipal Tank / Upper shell / Seam V-08	Human-reviewed finding DW-FND-NWT-001	Targeted investigation Qualified review follows

Recommended further investigation

Obtain coating-specialist review, ultrasonic thickness testing, and a bounded repair-scope determination.

Illustrative mock-up only. Measurements, findings, and dispositions require validation before issuance.